

HAD

EM

INNER

Temporary support

Flange

Rails

ACCESS

HAD

LAr Cal

AEJ


JM




FCAL


JNose


TAS


QUAD














HAD

EM

INNER

HAD

LAr Cal

AEJ

JM

FCAL

JNose


TAS


QUAD


ACCESS



Rails


10























































Beampipe supports





This support has to be attached.





























CRANE
ACCESS

Forward
Toroid

JToroid

HAD

HAD

EM

LAr Cal

AEJ

INNER

JM

FCAL

JDisk


JNose


TAS


QUAD


ACCESS

ACCESS












Beampipe supports



This support has to be locked.



This support has to be attached and the rolling support has to be removed.

